

Shipping instruction



Thank you very much for your calibration order.

Please ship your pyranometers to our address below:

EKO Instruments Europe
Lulofsstraat 55, Unit 28
2521 AL, Den Haag, The Netherlands

Attn. Ferry Koene / Rika Ishii
P. +31 (0) 70 305 0117
sales-eu@eko-instruments.com

*Please add 'for calibration' in reference

Packing instruction


If you keep an original box of a EKO pyranometer, please reuse it again for shipment. Otherwise please follow the below instruction to pack your pyranometers well so that they do not get damaged during transportation. The client is responsible for packing and shipping (fee).



1. Chose the right box - It should be thick enough to hold pyranometers and to protect the contents during transportation.



2. Pack well - Wrap each sensor with many layers of protection materials. Especially the glass dome is very fragile and must be well protected. Please make sure to tape around to fix the protection around the sensor. Also fill up the box with protection materials so that the sensors do not move in the box during transportation.



HANDLE WITH CARE

3. Seal the box - tightly with a thick tape. Put "HANDLE WITH CARE" sticker or anything equivalent.