

Change Notes / Release Notes:

v241108n (2024-11-08):

!!!-!!!: New "ASI16-Installer_v24" replaces previous "ASI-Manager" and "Support.exe".
New "ASI-Software" can be installed by using latest "ASI16-Installer_V24", only!
Previous "ASI-Managers" will NOT work to update any newer "ASI Software"!
New "ASI16-Installer_v24" also replaces previous "ASI_DHCP_Fix-It.jar" tool.

IMP: Life data cloudiness values displayed with one decimal place only.

FIX: Sometimes login to ASI GUI has required multiple (>5) tries to enter password.

FIX: Time configuration, interval setting lost after having switched to "Manual Time".

FIX: Time configuration, time was synchronized with NTP server even if deactivated.

FIX: Sometime changes in local ASI settings (capture, locale, ...) cannot be stored.
Sometimes shooting and FTP upload did not run, esp. after parameter change.

FIX: Old "life date" remain displayed in GUI even if "life data" function was disabled.

FIX: Sometimes shooting hang-up or GUI block after running for multiple (5-30) days.

FIX: Wrong internal link for CMS/Agent logo in Web-GUI.

FIX: Manuel reset of FTP connection did not work as should.

v240531n (2024-05-31):

NEW: GUI-Home: Cloud Analysis (CMS FCT) – Display of real-time analysis data.
See § 6.5, page 39.

NEW: Additional Capture/Shooting Template - Intervals: A= 5 Min., and B= 1 Min..
See § 6.8.2, page 44.

NEW: Remote access for ASI-16 V24 via CMS "REM" (VPN) encrypted tunnel.
See § 6.12, page 48.

IMP: Improved Peripheral Controller support for EKO MS-40S Pyranometers.
ASI SW, ASI16-Installer, CRM: Multiple minor improvements and fixes.